

Inspection Photos

Location Name: TEP Rocky Mountain LLC HARRIS RWF 31-5 Pad

Location # 311677



Photo # 5333 From entrance to location



Photo # 5334 From entrance to location

Location Name: TEP Rocky Mountain LLC HARRIS RWF 31-5 Pad
Location # 311677




Photo # 5336 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC HARRIS RWF 31-5 Pad

Location # 311677



Photo # 5337 Location



Photo # 5338 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC HARRIS RWF 31-5 Pad

Location # 311677



Photo # 5339 Location



Photo # 5340 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC HARRIS RWF 31-5 Pad

Location # 311677



Photo # 5341 Stored vehicles & boat in the interim area



Photo # 5342 Stored vehicles, boats & misc in the interim area

Inspection Photos

Location Name: TEP Rocky Mountain LLC HARRIS RWF 31-5 Pad

Location # 311677



Photo # 5343 Stored camper & debris on location



Photo # 5344 Stored camper & debris on location

Inspection Photos

Location Name: TEP Rocky Mountain LLC HARRIS RWF 31-5 Pad

Location # 311677



Photo # 5345 Debris/trash



Photo # 5346 Debris/trash

Inspection Photos

Location Name: TEP Rocky Mountain LLC HARRIS RWF 31-5 Pad

Location # 311677



Photo # 5347 Debris/trash



Photo # 5348 Debris/trash

Inspection Photos

Location Name: TEP Rocky Mountain LLC HARRIS RWF 31-5 Pad

Location # 311677



Photo # 5349 Battery sign weathered & cracking/starting to become illegible