

Operator: 8 North

Location Name: Silverback 36-A Pad

Loc ID: 443555

Inspection: 696300989



Exhibit A



Exhibit B

CA: Both Wellheads are missing the wellhead signs: Install sign to comply with Rule 210.b

CA Resolution: Operator has provided photo evidence showing that signs have been installed on both wellheads to comply with Rule 210.b.