

## Inspection Photos


Location Name: CAERUS PICEANCE LLC, CLEM-67S95W/15NENE

Location ID: 324017

Date: 8/8/2024



Location Entrance – Photo #02726



Wellhead – Photo #02730

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, CLEM-67S95W/15NENE

Location ID: 324017

Date: 8/8/2024



Separator – Photo #02728



Tank Battery – Photo #02731

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, CLEM-67S95W/15NENE

Location ID: 324017

Date: 8/8/2024



**Gas Meter – Photo #02727**