

Final Reclamation and Stormwater Inspection

Date: 08/06/2024

Operator: PDC ENERGY INC- 69175

Location ID: 302303

Inspection Document #: 708201485

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Rothe 29BU
Location ID: 302303



Photo 1. Taken south of the former tank battery and well location. Photo illustrates the access road does not appear to have been reclaimed with road base still present.



Photo 2. Southeast corner of the former tank battery location. The location does not appear to be progressing towards reclamation standards and regulations with the presence of bare soil and undesirable vegetation (e.g. kochia) observed.



Photo 3. Southwest corner of the former tank battery; see comments in Photo 2.

Inspection Photos
Location Name: Rothe 29BU
Location ID: 302303



Photo 4. Northwest corner of the former tank battery; see comments in Photo 2.

Inspection Photos
Location Name: Rothe 29BU
Location ID: 302303



Photo 5. Northeast corner of the former tank battery; see comments in Photo 2.

Inspection Photos
Location Name: Rothe 29BU
Location ID: 302303



Photo 6. Facing north at the former well location. Additional reclamation activities are required to comply with Rule 1004.