

# Final Reclamation and Stormwater Inspection

Date: 08/06/2024

Operator: BONANZA CREEK ENERGY OPERATING  
COMPANY LLC - 8960

Location ID: 305107

Inspection Document #: 708201493

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Wetco Farms 11-4  
Location ID: 305107



**Photo 1.** Facing northeast. The former well location does not appear to be progressing towards Final Reclamation standards and regulations. The reclaimed area has evidence of subsidence and is not reflective of the adjacent reference area crop with non-uniform vegetation cover observed.

Inspection Photos  
Location Name: Wetco Farms 11-4  
Location ID: 305107



**Photo 2.** Facing northwest; see comments in Photo 1.

Inspection Photos  
Location Name: Wetco Farms 11-4  
Location ID: 305107



**Photo 3.** Facing southwest; see comments in Photo 1.

Inspection Photos  
Location Name: Wetco Farms 11-4  
Location ID: 305107



**Photo 4.** Adjacent reference area photo taken northeast of the former well location.