

Inspection Photos

Location Name: EDENS-66N63W/18SWNW

Location ID: 305991




Photo #1

Edens 12-18 (123-23788) Wellsite
Temporarily Abandoned | TA



Photo #2

Edens 11-18*, 18-52, 12-18 Battery site
Inactive | Shut-down
Equipment Documented; Loc ID: 305590



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: EDENS-66N63W/18SWNW

Location ID: 305991



Photo #3

Edens 11-18*, 18-52, 12-18 Battery site

Inactive | Shut-down

Battery, wellsite(s) entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources