

Inspection Photos

API: 071-09287

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 8/12/2024

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing northwest at the beginning of the access road that remains by approved variance.



Inspection Photos



Photo 2. Facing southwest along the side of access road. The Russian olive tree has been removed.



Inspection Photos



Photo 3. Facing west toward the location..



Inspection Photos



Photo 4. The center of the location has been seeded and hydromulched..

