

Inspection Photos

API: 071-09246

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 8/12/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing south east along the access road near the location.



Inspection Photos



Photo 3. Facing east at the fill slope. There is an electric utility that remains at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-09246 | Date: 8/12/2024

Inspection Photos



Photo 4. Facing east at the location. The weeds have been controlled and this area was reseeded and hydromulched.



Inspection Photos



Photo 5. Facing northeast at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-09246 | Date: 8/12/2024