

# Inspection Photos

API: 071-08159

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 8/12/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest along the access road. There is erosion along the roadside that will need BMP's.





## Inspection Photos



**Photo 2.** Facing southwest toward the wellsite.





## Inspection Photos



**Photo 3.** There are undesirable weeds at the center of the location that should be controlled/mowed. Russian thistle known as Tumble weeds can cause debris issues.

