

Environmental Inspection

August 5, 2024

Operator: KP KAKUFFMAN - #46290

Facility ID: 480891; South McCallum TB

API: 05-057-06320

Inspection Document #: 71200011

Jackson County, CO

NWSW Section 27 T9N R78W

Alex Fischer
Environmental Supervisor - Western
Colorado, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: South McCallum Tank Battery

Facility ID: 480891

Date: August 5, 2024



Photo 1. Signage at Separator. Emergency contact number illegible.



Inspection Photos

Location Name: South McCallum Tank Battery

Facility ID: 480891

Date: August 5, 2024



Photo 2. Improper storage of E&P Waste in 5-gallon buckets (Rule 905.a.(1)).



Inspection Photos

Location Name: South McCallum Tank Battery

Facility ID: 480891

Date: August 5, 2024



Photo 3. Oily rag and oil inside of generator cabinet.



Photo 4. Oily rag and oil inside of generator cabinet.



Inspection Photos

Location Name: South McCallum Tank Battery

Facility ID: 480891

Date: August 5, 2024



Photo 5. Lube oil staining on ground beneath generator.



Photo 6. Lube oil on the ground and timber beneath generator.



Inspection Photos

Location Name: South McCallum Tank Battery

Facility ID: 480891

Date: August 5, 2024



Photo 7. Oil staining on the ground at well head.



Photo 8. Trash debris throughout location.



Inspection Photos

Location Name: South McCallum Tank Battery

Facility ID: 480891

Date: August 5, 2024



Photo 9. Trash, debris, and vegetation throughout location.



Photo 10. Trash, debris, and vegetation throughout location.



Inspection Photos

Location Name: South McCallum Tank Battery

Facility ID: 480891

Date: August 5, 2024



Photo 11. Tank battery looking south to southeast.



Photo 12. Tank battery looking west to northwest.



Inspection Photos

Location Name: South McCallum Tank Battery

Facility ID: 480891

Date: August 5, 2024



Photo 13. Emergency contact number illegible.



Photo 14. Evidence of livestock on tank battery berms.



Inspection Photos

Location Name: South McCallum Tank Battery

Facility ID: 480891

Date: August 5, 2024



Photo 15. Open line and evidence of livestock.



Photo 16. Staining on tank beneath threaded nipple to valve.



Inspection Photos

Location Name: South McCallum Tank Battery

Facility ID: 480891

Date: August 5, 2024



Photo 17. Evidence of livestock and insufficient berm.



Photo 18. Firetube partial buried.



Inspection Photos

Location Name: South McCallum Tank Battery

Facility ID: 480891

Date: August 5, 2024



Photo 19. Wellhead sign.



Photo 20. Pumpjack with vegetation.



Inspection Photos

Location Name: South McCallum Tank Battery

Facility ID: 480891

Date: August 5, 2024



Photo 21. Oil weeping from valve on Tank # 157271_111716



Photo 22. Trash/debris or unused equipment (extension cord).

