

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-27

Location ID: 335479



Photo # 4349 From entrance to location



Photo # 4350 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-27

Location ID: 335479



Photo # 4351 Location



Photo # 4352 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-27

Location ID: 335479



Aug 1, 2024 at 11:16:47 AM

Photo # 4353 Location



Aug 1, 2024 at 11:22:21 AM

Photo # 4354 Production tank damaged

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 413-27

Location ID: 335479



Photo # 4355 Production tank damaged



Photo # 4356 Production tank damaged