

Beeman
Grassy creek #1
Location ID: 316741



Location



Stored hot oiler

Beeman
Grassy creek #1
Location ID: 316741



Well head / location



Well head / location

Beeman
Grassy creek #1
Location ID: 316741



Well head



Unused equipment

Beeman
Grassy creek #1
Location ID: 316741



Unused equipment




Unused equipment

Beeman
Grassy creek #1
Location ID: 316741



Staining



Separator spark arrester cover not installed

Beeman
Grassy creek #1
Location ID: 316741



Access road lacks stabilization and shows erosion



Access road lacks stabilization and shows erosion