



# Denova Sequestration FIRR Images

Inspection Document #: 708201343

**Carbon  
America**

Making climate change history™



Photo 1: The new location of the trailer that has been moved off the oil and gas location to adjacent property with approval from the landowner (Photo July 22, 2024).



Photo 2: Erosion repair near the cattle guard and entrance to the well pad (Photo July 25, 2024).



Photo 3: Erosion repair along the road to the well pad (Photo July 25, 2024).



Photo 4: Erosion repair along the road to the well pad (Photo July 25, 2024).



Photo 5: Erosion repair along the road to the well pad (Photo July 25, 2024).



Photo 6: Erosion repair along the road to the well pad (Photo July 25, 2024).



Photo 7: Erosion repair along the road to the well pad (Photo July 25, 2024).



Photo 8: Erosion repair and BMP installation on the well pad (Photo July 25, 2024).



Photo 9: Erosion repair and BMP installation on the well pad



Photo 10: Erosion repair and BMP installation on the well pad (Photo July 25, 2024).



Photo 11: Erosion repair and BMP installation on the well pad (Photo July 25, 2024).



Photo 12: Erosion repair and BMP installation on the well pad (Photo July 25, 2024).



Photo 13: Oil staining removal on the well pad (Photo July 25, 2024).



Photo 15: Oil staining removal on the well pad (Photo July 25, 2024).



Photo 16: Oil staining removal on the well pad (Photo July 25, 2024).