

Inspection Photos

August 6th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 325480

Inspection Document #: 714001066

La Plata County, CO

Township: SWNE 3 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Burkett 1-3
Location ID: 325480




Photo 1. View of the location taken from the access point facing center.

Inspection Photos
Location Name: Burkett 1-3
Location ID: 325480



8/6/24
+37.246498,-107.729118
263° W

Photo 2. Patches of flowering Musk thistle observed in the southern portion of the disturbance.

Inspection Photos
Location Name: Burkett 1-3
Location ID: 325480

8/6/24
+37.246780,-107.729415
50° NE



Photo 3. View of rill/gully erosion forming in the southwest corner of the disturbance. Storm water BMPs/controls are needed in this area.

Inspection Photos
Location Name: Burkett 1-3
Location ID: 325480



Photo 4. Reference area comprised of Juniper, Antelope bitterbrush and Smooth brome.