

# Inspection Photos

August 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333113

Inspection Document #: 714001068

La Plata County, CO

Township: SENE 12 32N 10W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Margaret Montgomery A 1  
Location ID: 333113

8/12/24  
+37.034162,-107.879563  
141° SE




**Photo 1.** View of the location taken from the access point facing center.



## Inspection Photos

Location Name: Margaret Montgomery A 1

Location ID: 333113



**Photo 2.** View of weedy Kochia and Russian thistle observed throughout the location. This is considered debris and needs to be removed.



Inspection Photos  
Location Name: Margaret Montgomery A 1  
Location ID: 333113



**Photo 3.** Unlabeled tank on location.





Inspection Photos

Location Name: Margaret Montgomery A 1

Location ID: 333113



8/12/24

+37.033919,-107.880736

242° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area comprised Western wheatgrass, Sand dropseed and Prairie sunflower.

API #: 067-07521