

Inspection Photos

August 12th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 325012

Inspection Document #: 714001069

La Plata County, CO

Township: SENE 13 32N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Sever 1
Location ID: 325012

8/12/24
+37.019287,-107.879664
353° N



8/12/24
+37.019311,-107.879657
337° NW

Photo 1. View of the location taken from the access point facing center.

Inspection Photos
Location Name: Sever 1
Location ID: 325012



Photo 2. Patch of flowering musk thistle observed on the eastern edge of the disturbance.

Inspection Photos
Location Name: Sever 1
Location ID: 325012




Photo 3. View of stormwater issues observed along the access road. Additional stabilization is needed to minimize degradation to the access road.

Inspection Photos
Location Name: Sever 1
Location ID: 325012

8/12/24
+37.019346,-107.879407
148° SE



Photo 4. Reference area comprised predominantly of Sagebrush and Sand dropseed.