

Inspection Photos

08/09/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335294

Inspection Doc: 696206108

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335294



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335294



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335294



Photo 3: Lines at tank missing cap/plug. Produced fluids within containment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335294



Photo 4: Photos taken from the south end of the Location. Photos show hay storage in close proximity of production equipment on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335294



Photo 5: Photos 5-8 taken from the interim areas of the Location. Photos show that interim reclamation is not progressing towards ECMC 1003 Reclamation requirements; interim areas are predominantly bare, or vegetated by Undesirable Plant Species. Perennial establishment that was observed was sparse.

Noxious weed establishment, including Jointed Goatgrass and Field Bindweed observed throughout interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335294



Photo 6: See comments under photo 5.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335294



August 9, 2024



August 9, 2024

Photo 7: See comments under photo 5.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335294



Photo 8: See comments under photo 5. Photo left example showing Jointed Goatgrass establishment on the interim areas; photo right example showing Field Bindweed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources