

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403870947  
Receive Date:  
07/30/2024  
Report taken by:  
Chris Sanchez

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>EVERGREEN NATURAL RESOURCES LLC</u>	Operator No: <u>10705</u>	<b>Phone Numbers</b>
Address: <u>1875 LAWRENCE ST STE 1150</u>		Phone: <u>(719) 2204330</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>( )</u>
Contact Person: <u>Timothy Fernandez</u>	Email: <u>timothy.fernandez@enrllc.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 36644 Initial Form 27 Document #: 403870947

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: \_\_\_\_\_

SITE INFORMATION

No  Multiple Facilities

Facility Type: <u>SPILL OR RELEASE</u>	Facility ID: <u>486525</u>	API #: _____	County Name: <u>LAS ANIMAS</u>
Facility Name: <u>Lorencito 13-17 Spill</u>	Latitude: <u>37.079951</u>	Longitude: <u>-104.809536</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>SWSW</u>	Sec: <u>17</u>	Twp: <u>34S</u>	Range: <u>66W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use Non-Crop Land  
Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? No  
Is groundwater less than 20 feet below ground surface? No

### SITE INVESTIGATION PLAN

#### TYPE OF WASTE:

- E&P Waste       Other E&P Waste       Non-E&P Waste
- Produced Water       Workover Fluids
- Oil       Tank Bottoms
- Condensate       Pigging Waste
- Drilling Fluids       Rig Wash
- Drill Cuttings       Spent Filters
- Pit Bottoms
- Other (as described by EPA)

#### DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	765 sq ft	Visual Inspection

#### INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

The spill was discovered by an ECMC inspector and was reported via email to ENR staff. Upon inspection, white staining from the historical spill was discovered along the spill path, originating at the wellhead. The packing was no longer leaking. The spill appears to have originated from the packing of the wellhead, ran 70 feet south across the location, and flowed an additional 75 feet south off location to a road below. The spill continued to flow down a bar ditch along the road southeast for an additional 110 feet. The spill did not come into contact with any live water and did not affect any state waters.

#### PROPOSED SAMPLING PLAN

##### Proposed Soil Sampling

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Soil samples have been collected at three points along the spill path. A sample was collected near the wellhead at the area of greatest impact and analyzed for Full 915-1 Analytes. Two other sites along the spill path were sampled and analyzed for 915-1 Soil Suitability for Reclamation and Metals. A native sample was collected and analyzed for 915-1 Metals. Results are pending.

##### Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

##### Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

##### Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

### SITE INVESTIGATION REPORT

#### SAMPLE SUMMARY

**Soil**

Number of soil samples collected 0  
Number of soil samples exceeding 915-1 \_\_\_\_\_  
Was the areal and vertical extent of soil contamination delineated? Yes  
Approximate areal extent (square feet) 765

**NA / ND**

\_\_\_\_\_ Highest concentration of TPH (mg/kg) \_\_\_\_\_  
\_\_\_\_\_ Highest concentration of SAR \_\_\_\_\_  
\_\_\_\_\_ BTEX > 915-1 \_\_\_\_\_  
\_\_\_\_\_ Vertical Extent > 915-1 (in feet) \_\_\_\_\_

**Groundwater**

Number of groundwater samples collected 0  
Was extent of groundwater contaminated delineated? No  
Depth to groundwater (below ground surface, in feet) \_\_\_\_\_  
Number of groundwater monitoring wells installed \_\_\_\_\_  
Number of groundwater samples exceeding 915-1 \_\_\_\_\_

\_\_\_\_\_ Highest concentration of Benzene (µg/l) \_\_\_\_\_  
\_\_\_\_\_ Highest concentration of Toluene (µg/l) \_\_\_\_\_  
\_\_\_\_\_ Highest concentration of Ethylbenzene (µg/l) \_\_\_\_\_  
\_\_\_\_\_ Highest concentration of Xylene (µg/l) \_\_\_\_\_  
\_\_\_\_\_ Highest concentration of Methane (mg/l) \_\_\_\_\_

**Surface Water**

0 Number of surface water samples collected  
\_\_\_\_\_ Number of surface water samples exceeding 915-1  
If surface water is impacted, other agency notification may be required.

**OTHER INVESTIGATION INFORMATION**

- Were impacts to adjacent property or offsite impacts identified?
- Were background samples collected as part of this site investigation?
- Was investigation derived waste (IDW) generated as part of this investigation?  
Volume of solid waste (cubic yards) \_\_\_\_\_ Volume of liquid waste (barrels) \_\_\_\_\_
- Is further site investigation required?

**REMEDIAL ACTION PLAN**

**SOURCE REMOVAL SUMMARY**

Describe how source is to be removed.

Natural attenuation.

**REMEDIATION SUMMARY**

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

909j results indicate the absence of VOCs. Natural attenuation will be utilized at this site.

**Soil Remediation Summary**

In Situ

Ex Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction

\_\_\_\_\_ Excavate and offsite disposal  
If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_  
Name of Licensed Disposal Facility or ECMC Facility ID # \_\_\_\_\_

Yes Natural Attenuation  
 Other \_\_\_\_\_

Excavate and onsite remediation  
 Land Treatment  
 Bioremediation (or enhanced bioremediation)  
 Chemical oxidation  
 Other \_\_\_\_\_

**Groundwater Remediation Summary**

Bioremediation ( or enhanced bioremediation )  
 Chemical oxidation  
 Air sparge / Soil vapor extraction  
 Natural Attenuation  
 Other \_\_\_\_\_

**GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

### Approved Reporting Schedule:

Quarterly     Semi-Annually     Annually     Other

### Request Alternative Reporting Schedule:

Semi-Annually     Annually     Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:     Groundwater Monitoring     Land Treatment Progress Report     O&M Report  
 Other Soil \_\_\_\_\_

## Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Operator does not have site-specific financial assurance for this project, however Operator has inactive well, blanket and surface bonding, as well as commercial general liability and/or umbrella/excess insurance meeting the requirements of 705.b. Operator does not anticipate making an insurance claim for this report. Assessment activities as outlined herein are proposed. Costs included herein are estimates only and they may change over time base on numerous factors. Accordingly, Operator makes no guarantee as to the accuracy of such cost estimates, thus providing that estimate for the next year below.

Operator anticipates the remaining cost for this project to be: \$ 0 \_\_\_\_\_

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No \_\_\_\_\_

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_

E&P waste (solid) description \_\_\_\_\_

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_

E&P waste (liquid) description \_\_\_\_\_

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: \_\_\_\_\_

# RECLAMATION PLAN

## RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

No reclamation is necessary at this site.

Is the described reclamation complete? \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim  Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

## SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. \_\_\_\_\_

Proposed date of completion of Reclamation. \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 04/26/2024

Actual Spill or Release date, or date of discovery. 04/25/2024

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 04/25/2024

Proposed site investigation commencement. 04/25/2024

Proposed completion of site investigation. 08/31/2024

### REMEDIAL ACTION DATES

Proposed start date of Remediation. 04/25/2024

Proposed date of completion of Remediation. 08/31/2024

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

**OPERATOR COMMENT**

This Form 27 is being submitted as a continuation of remediation activities at the Lorencito 13-17 spill. Soil sample results are still pending at the time of this filing.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Timothy Fernandez

Title: Regulatory Supervisor

Submit Date: 07/30/2024

Email: timothy.fernandez@enrllc.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Chris Sanchez

Date: 08/14/2024

Remediation Project Number: 36644

**COA Type****Description**

	Upon approval of this Form 27i the Operator shall submit a Supplemental Form 19 Requesting Closure of Spill Facility ID 486525
	Operator shall provide Analytical results in a Form 27 Supplemental submission as soon as they are available
	Operator shall continue Quarterly Reporting until the Site Assessment is completed and the remediation area demonstrates Compliance with Table 915-1 Standards.

3 COAs

**ATTACHMENT LIST**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

403870947	INVESTIGATION/REMEDATION WORKPLAN (INITIAL)
403870984	SOIL SAMPLE LOCATION MAP
403870986	OTHER
403889309	FORM 27-INITIAL-SUBMITTED

Total Attach: 4 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)