

Operator: 8 NORTH LLC

Location Name: KALIA-611N61W 11SWNW

Loc ID: 302348

Inspection: 696300860




8 North, LLC

720.370.5540

KALIA 5-11

SW/4 NW/4 SEC.11-T11N-R61W





CA: Stained Soil at Exhaust and Engine. Properly treat or dispose of oily waste in accordance with 907.e.

CA Resolution: Operator has provided photo evidence showing that the stained soil at the wellhead has been addressed in compliance with the 900 and 600 series.