


Operator: 8 NORTH LLC

Location Name: LOYD FARMS-612N61W 32NENW

Loc ID: 302821

Inspection: 696300979







CA: Stained Soil at Exhaust and Wellhead, see photos 2 and 3. Mechanical condition Comply with Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.e.

CA Resolution: Operator has provided photo evidence showing that the stained soil at the wellhead has been addressed in compliance with the 900 and 600 series.