

# Inspection Photos

08/09/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 335055

**Inspection Doc:** 696206116

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335055



**Photo 1:** Photos 1-2 taken from the north end of the Location. Photos provide an overview from east, southeast, southwest to west.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335055




**Photo 2:** See comments under photo 1.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335055



**Photo 3:** Photo shows the CSF 31B-07-07-91 Well (API 05-045-11983). Gas heard leaking from well. Operator was provided notice at time of inspection.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335055



**Photo 4:** Photos 4-5 example showing anchors missing required marking, or marker is in disrepair.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335055



August 9, 2024

**Photo 5:** See comments under photo 4.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335055



**Photo 6:** Photo taken from the battery facility. Photo shows unused pipe stored in containment. Photo also show stained soils due to spill.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335055



**Photo 7:** Labels at container no longer legible.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335055



**Photo 8:** Photos examples showing unused risers remaining on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335055



**Photo 9:** Photos taken from the interim areas on the south and north ends of the Location. Vegetation observed is predominantly perennial plant species; establishment is uniform. Noxious weeds not observed at time of inspection.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources