

Final Reclamation and Stormwater Inspection

Date: 08/13/2024

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 318948

Inspection Document #: 708201510

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Ottesen #1
Location ID: 318948



Photo 1. Taken from the southwest corner of the former location. Reclamation rules require reclamation activities to be conducted within twelve months of plugging on non-cropland. Well was plugged 04/12/2021. It does not appear any reclamation work has been performed as gravel remains throughout the former location. Location is not reflective of adjacent reference areas as it is predominantly exposed/bare soil.

Inspection Photos
Location Name: Ottesen #1
Location ID: 318948



Photo 2. Taken from the southeast corner of the former location; See comments in Photo 1.

Inspection Photos
Location Name: Ottesen #1
Location ID: 318948



Photo 3. Taken from the center portion of the location, facing north. See comments in Photo 1.

Inspection Photos
Location Name: Ottesen #1
Location ID: 318948



Photo 4. Taken from the northern portion of the location, facing south. See comments in Photo 1.