


**Operator: 8 NORTH LLC**


**Location Name: LOYD FARMS-612N61W 32SWSE**

**Loc ID: 302818**

**Inspection: 696300975**







**CA:** Stained Soil at Exhaust and Gas Engine, see photos 3, 4, & 5. Mechanical condition Comply with Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.e.

**CA Resolution:** Operator has provided photo evidence showing that the stained soil has been appropriately addressed to comply with the 600 and 900 series.