

# Inspection Photos

API: 071-09472

Operator: OGRIS OPERATING LLC

Inspection Date: 8/14/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the wellsite.





## Inspection Photos



**Photo 2.** There is still oily fluid in the engine skid. It appears fresh base was placed where staining occurred. Stained soils should be removed and disposed.

