

Attachment B

Photographic Log



Equipment ID: FL01-01		Equipment Type:			Equipment ID: FL01-02		Equipment Type:		
Material:	Volume:	Contents:			Material:	Volume:	Contents:		
Notes/Conditions:					Notes/Conditions:				

Photographic Log





Equipment ID: FL01-03		Equipment Type:		Equipment ID: FL01-04		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

					
<p>Material:</p>	<p>Volume:</p>	<p>Contents:</p>	<p>Equipment ID: FL01-06 Equipment Type:</p>		
<p>Notes/Conditions:</p>			<p>Material:</p>	<p>Volume:</p>	<p>Contents:</p>
<p>Notes/Conditions:</p>			<p>Notes/Conditions:</p>		

Photographic Log

					
Equipment ID: FL01-07		Equipment Type:	Equipment ID: FL01-08		Equipment Type:
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions:			Notes/Conditions:		

Photographic Log



Equipment ID: FL01R-W@4'		Equipment Type:		Equipment ID: BK01		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: Facing west			

Equipment ID: WHS01-W		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			



Equipment ID: WHS01-N		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID: WHS01-E		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			



Equipment ID: WHS01-S		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID: WH01-N		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			



Equipment ID: WH01-E		Equipment Type:		Equipment ID: WH01-S		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			



Equipment ID: WH01-W		Equipment Type:		Equipment ID: Facing W		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions: Cut and capped WH			



TANK BATTERY DECOMMISSIONING FORM

SITE NAME: GEMINI K 1-9, 10 TANK BATTERY							DATE: 5/13/2024	REM. PROJECT #: 35296	WEATHER: 60S SUNNY		
SITE DIRECTIONS: CR 35 & 48, E 0.9 mi, NE 0.15 mi, N 0.25 mi, W INTO							CLIENT: PDC				
LEGALS AND LAT/LONG: 40.339521, -104.716204							TASMAN PERSONNEL: RY				
SOIL TYPES: Well Graded Sand - SW							SURFACE GRADIENT: North				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)		4		
5/13/2024 09:03	FLARE01@0-6"	0.0	No Staining	No Odor	Yes	Grab	Buried or Partially Buried Vessel		3		
5/13/2024 09:04	FLARE02@0-6"	0.0	No Staining	No Odor	Yes	Grab	Separator		3		
5/13/2024 09:05	MH01@0-6"	0.0	No Staining	No Odor	Yes	Grab	Emission Control Device (ECD)		2		
5/13/2024 09:06	MH02@0-6"	0.0	No Staining	No Odor	Yes	Grab	Dump Line		3		
5/13/2024 09:09	SEP01-FL@3'	0.0	No Staining	No Odor	Yes	Lab	Wellhead				
5/13/2024 09:20	SEP02-FL@3'	0.1	No Staining	No Odor	Yes	Lab	Flowline		2		
5/13/2024 09:34	SEP03-FL@3'	0.1	No Staining	No Odor	Yes	Lab	Other: METER HOUSE		2		
5/13/2024 09:50	SEP01-DL@3'	0.0	No Staining	No Odor	Yes	Lab	Soil Loads Removed				
5/13/2024 10:02	SEP02-DL@3'	0.0	No Staining	No Odor	Yes	Lab	IMPACTED SOIL IDENTIFIED?				
5/13/2024 10:20	SEP03-DL@3'	0.0	No Staining	No Odor	Yes	Lab	ESTIMATED VOLUME OF IMPACTS:				
5/13/2024 13:16	AST01@0-6"	0.0	No Staining	No Odor	Yes	Lab	Date		Number	CY	
5/13/2024 13:20	AST02@0-6"	0.2	No Staining	No Odor	Yes	Lab					
5/13/2024 13:24	AST03@0-6"	0.0	No Staining	No Odor	Yes	Lab					
5/13/2024 13:28	AST04@0-6"	0.0	No Staining	No Odor	Yes	Lab					
5/14/2024 08:59	FLARE03@0-6"	0.0	No Staining	No Odor	Yes	Grab					
5/14/2024 09:23	BKG01@0-6"	0.0	No Staining	No Odor	Yes	Lab	Total Removed		0	0	
5/14/2024 09:24	BKG01@2.5'	0.0	No Staining	No Odor	Yes	Lab	Disposal Facility:				
5/14/2024 09:25	BKG01@3'	0.0	No Staining	No Odor	Yes	Lab	Groundwater Recovery				
5/14/2024 09:26	BKG01@4'	0.0	No Staining	No Odor	Yes	Lab	DATE GW ENCOUNTERED:			DEPTH:	
5/14/2024 09:27	BKG01@5'	0.0	No Staining	No Odor	Yes	Lab	GROUNDWATER IN CONTACT WITH IMPACTED SOIL?				
							LNAPL OR SHEEN OBSERVED ON GW?				
GROUNDWATER SAMPLING							Date		BBLs		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
							Total Removed		0		
							Disposal Facility:				

Photographic Log



Equipment ID: FLARE01		Equipment Type:		Equipment ID: FLARE02		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			


Photographic Log




Equipment ID: MH01		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID: MH02		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Photographic Log



Equipment ID: SEP01-FL		Equipment Type:		Equipment ID: SEP02-FL		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log


Equipment ID: SEP03-FL		Equipment Type:		Equipment ID: SEP01-DL		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log



Equipment ID: SEP02-DL		Equipment Type:		Equipment ID: SEP03-DL		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

								
						Equipment ID: _{AST01}		
Material:		Volume:	Contents:		Equipment ID: _{AST02}		Equipment Type:	
Notes/Conditions:			Notes/Conditions:					

Photographic Log

					
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions:			Notes/Conditions:		

Photographic Log



Equipment ID: FLARE03		Equipment Type:		Equipment ID: BK01		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			