

# Inspection Photos

08/09/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 323875

**Inspection Doc:** 696206124

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323875



August 9, 2024



August 9, 2024

**Photo 1:** Photos taken from the east end of the Location. Photos provide an overview of the Location from southwest to northwest. Location is not progressing towards 1004 reclamation standards; perennial establishment is not uniform and location is predominantly bare, or vegetated by Undesirable Plant Species, including noxious weeds such as Jointed Goatgrass and Knapweed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323875



**Photo 2:** Photo left taken from the south end of the Location, facing north. Photo right taken from the north end of the Location, facing south. Location is not progressing towards 1004 reclamation standards; perennial establishment is not uniform and location is predominantly bare, or vegetated by Undesirable Plant Species, including noxious weeds such as Jointed Goatgrass and Knapweed.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323875



August 9, 2024



August 9, 2024

**Photo 3:** Photos examples showing perennial establishment is not uniform and location is predominantly bare, or vegetated by Undesirable Plant Species, including noxious weeds such as Jointed Goatgrass and Knapweed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323875



**Photo 5:** Photos examples showing Jointed Goatgrass and Knapweed establishment on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323875



**Photo 1:** Photo taken from the access road facing north; O&G Access road to Location has not been reclaimed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323875



**Photo 4:** Photo taken from the adjacent reference area for comparison to establishment on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources