

Inspection Photos

08/09/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 423439

Inspection Doc: 696206128

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 423439



Photo 1: Photos taken from the east end of the Location. Photos provide an overview of the working pad from southeast, south, west to northwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 423439



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 423439



Photo 3: Photos 3-5 taken from the interim areas of the Location. Photos examples showing Location is not progressing towards 1003 reclamation standards; perennial establishment is not uniform and location is predominantly bare or vegetated by Undesirable Plant Species.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 423439



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 423439



August 9, 2024

Photo 5: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 423439



Photo 6: Photos examples of the adjacent reference areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources