

Inspection Photos

08/09/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383325

Inspection Doc: 696206130

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383325



August 9, 2024



August 9, 2024

Photo 1: Photos taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383325



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383325



Photo 3: Photos 3-4 taken from the interim areas of the Location. Photos examples showing Location is not progressing towards 1003 reclamation standards; perennial establishment is not uniform and location is predominantly bare or vegetated by Undesirable Plant Species.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383325



Photo 4: Photos examples of the adjacent reference areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383325



Photo 5: Unused equipment



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383325




Photo 6: Photo shows Unused equipment identified in previous inspections remains stored on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources