

# Inspection Photos

API: 071-09190

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 8/14/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest toward the access road. There is erosion along the road that will need to be repaired.





## Inspection Photos



**Photo 2.** Facing northwest along the access road. Stormwater is bypassing the culvert and is causing erosion of the road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 3.** Facing northwest toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:071-09190 | Date: 8/14/2024