

Livingston Pad

Spill Assessment and Liner Inspection


Extraction Oil and Gas

COGCC Facility ID: 455317

NWSE Sec 7 1S 68W



Release Discovery



View of ~ 5-gallon release entirely confined inside lined containment.

Site Cleanup




A vacuum truck was utilized to remove the impacted ballast material.

Liner Inspection




99°E (T) 39.977912°, -105.040048° ±13ft



359°N (T) 39.977876°, -105.040026° ±13ft



188°S (T) 39.977938°, -105.039991° ±13ft



An inspection was conducted on 8/16/2024 and the integrity of the liner was confirmed to be in satisfactory condition. No holes or tears were observed.