

Final Reclamation and Stormwater Inspection

Date: 08/13/2024

Operator: CRESTONE PEAK RESOURCES OPERATING
LLC - 10633

Location ID/ Well API: 331608/ 123-20976

Inspection Document #: 708201515

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Chapin 44-4
Location ID: 331608



Photo 1. Facing north at the former well location. Well API 123-20976 was plugged and abandoned on 04/09/2018. It does not appear that final reclamation activities have been performed since the well was plugged.

Inspection Photos
Location Name: Chapin 44-4
Location ID: 331608



Photo 2. Facing east; see comments in Photo 1.

Inspection Photos
Location Name: Chapin 44-4
Location ID: 331608



Photo 3. Facing southeast; see comments in Photo 1.

Inspection Photos
Location Name: Chapin 44-4
Location ID: 331608



Photo 4. Facing southwest; see comments in Photo 1.

Inspection Photos
Location Name: Chapin 44-4
Location ID: 331608



Photo 5. Taken near the southwestern portion of the expanded pad for Well API 123-20976. Photo illustrates erosion degradation (e.g gullying) originating from the pad with evidence of off location sediment deposition onto adjacent lands (Photo 6).

Inspection Photos
Location Name: Chapin 44-4
Location ID: 331608



Photo 6. Continued from Photo 5; facing southwest. Photo illustrates erosion degradation (e.g. gullying) and sediment deposition off location (indicated by red arrow).

Inspection Photos
Location Name: Chapin 44-4
Location ID: 331608



Photo 7. Google Earth aerial imagery taken circa (06/2017) prior to plugging and abandonment of Well API 123-20976. Red polygon illustrates approximate well footprint, not including access road to nearby well.

Inspection Photos
Location Name: Chapin 44-4
Location ID: 331608



Photo 8. Google Earth aerial imagery taken circa (09/2023) after Well API 123-20976 was plugged and abandoned. Red polygon illustrates approximate footprint of the well before P&A operations and the green polygon illustrates the pad expansion likely used for P&A operations that was not reclaimed per Rule 1004.