

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/27NWNW

Location ID: 335574

Date: 8/14/2024



Location Entrance – Photo #02804



Wellheads – Photo #02809

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/27NWNW

Location ID: 335574

Date: 8/14/2024



Gas Meters – Photo #02810



Gas Lift – Photo #02806

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/27NWNW

Location ID: 335574

Date: 8/14/2024



Gas Lift – Photo #02807



Gas Lift – Photo #02808

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/27NWNW

Location ID: 335574

Date: 8/14/2024



Chem Tanks – Photo #02805



Unsecured Meter House – Photo #02811