

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/27NWNW

Location ID: 335978

Date: 8/14/2024



Location Entrance – Photo #02814



Wellheads – Photo #02816

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/27NWNW

Location ID: 335978

Date: 8/14/2024



Gas Meters – Photo #02817



Gas Lift – Photo #02823

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/27NWNW

Location ID: 335978

Date: 8/14/2024



Tank Battery – Photo #02819



Chem Tanks – Photo #02822

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/27NWNW

Location ID: 335978

Date: 8/14/2024



Open-Ended Line – Photo #02818



Wildlife Entry Hazard – Photo #02820