


ATTACHMENT B



VILLAGE 16

Equipment ID: FL01R-S@5'		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID: FL01R-W@3'		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			



Equipment ID: FL01-1@3'		Equipment Type:		Equipment ID: BKG01@3'&BKG01@5'		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			



Equipment ID: WHS01-N @ 0-6"		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: PHOTO FACING SOUTH			



Equipment ID: WHS01-E @ 0-6"		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: PHOTO FACING WEST			


Equipment ID:WHS01-S @ 0-6"

Equipment Type:
Material:
Volume:
Contents:
Notes/Conditions:PHOTO FACING NORTH

Equipment ID:WHS01-W @ 0-6"

Equipment Type:
Material:
Volume:
Contents:
Notes/Conditions:PHOTO FACING EAST

					
Equipment ID: WH01-N @ 5'		Equipment Type: Wellhead	Equipment ID: WH01-E @ 5'		Equipment Type: Wellhead
Material: Steel	Volume:	Contents: Oil/Gas/Water	Material: Steel	Volume:	Contents: Oil/Gas/Water
Notes/Conditions: PHOTO FACING NORTH			Notes/Conditions: PHOTO FACING EAST		


Equipment ID:WH01-S @ 5'

Equipment Type: Wellhead

Material: Steel

Volume:
Contents: Oil/Gas/Water

Notes/Conditions: PHOTO FACING SOUTH

Equipment ID:WH01-W @ 5'

Equipment Type: Wellhead

Material: Steel


Volume:
Contents: Oil/Gas/Water

Notes/Conditions: PHOTO FACING WEST



Equipment ID: WH01 @ 6'		Equipment Type: Wellhead	
Material: Steel	Volume:	Contents: Oil/Gas/Water	
Notes/Conditions: PHOTO TAKEN FROM ABOVE EAST WALL			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: PRE DECOM reference photo			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: PRE DECOM reference photo			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions: POST DECOM reference photo			