

Inspection Photos

August 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325238

Inspection Document #: 714001076

La Plata County, CO

Township: SENW 1 32N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bonds 1
Location ID: 325238



Photo 1. View of the disturbance taken from the access point facing center.



API #: 067-05787

Inspection Photos
Location Name: Bonds 1
Location ID: 325238




Photo 2. Weedy kochia debris observed in large patches throughout the disturbance.

Inspection Photos
Location Name: Bonds 1
Location ID: 325238



Photo 3. Stormwater appears to be controlled at this time.



API #: 067-05787

Inspection Photos
Location Name: Bonds 1
Location ID: 325238



Photo 4. Reference area comprised of Juniper, Pine and Sagebrush.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-05787