

Inspection Photos

August 12th, 2024

Operator: Enduring Resources LLC - 10663

Location ID: 312122

Inspection Document #: 714001081

La Plata County, CO

Township: NENE 16 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Southern Ute 16-6
Location ID: 312122



8/12/24
+37.108172,-107.933699
298° NW



Photo 1. View of the disturbance taken from the access point facing center.

Inspection Photos
Location Name: Southern Ute 16-6
Location ID: 312122



Photo 2. Produced water tank label has been updated, capacity is not listed.

Inspection Photos
Location Name: Southern Ute 16-6
Location ID: 312122



8/12/24
+37.108472,-107.933948
316° NW

Photo 3. View of the western interim reclamation area facing northwest.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06288

Inspection Photos
Location Name: Southern Ute 16-6
Location ID: 312122

8/12/24
+37.108250,-107.933928
218° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area comprised of Intermediate wheatgrass, Rabbitbrush and Big Sagebrush.

API #: 067-06288