

Inspection Photos

August 12th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 325195

Inspection Document #: 714001082

La Plata County, CO

Township: NESE 15 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-10 23
Location ID: 325195

8/12/24
+37.100231,-107.915848
278° W



Photo 1. View of the project area taken from the eastern edge facing center.

Inspection Photos
Location Name: Bondad 33-10 23
Location ID: 325195

8/12/24
+37.100257,-107.915960
41° NE



Photo 2. View of the project area taken from the southern edge facing center.

Inspection Photos
Location Name: Bondad 33-10 23
Location ID: 325195



Photo 3. Large patch of weedy russian thistle debris observed in the center of the project area.

Inspection Photos

Location Name: Bondad 33-10 23

Location ID: 325195



8/12/24

+37.100323,-107.915783

132° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area comprised of Smooth brome, Juniper and Big sagebrush.

API #: 067-05589