

Inspection Photos
Location Name: Guadagnoli 2
Location ID: 318225



Photo 1 Location access road overgrow with vegetation



Photo 2 Wellsite overgrown with dead vegetation.

Inspection Photos
Location Name: Guadagnoli 2
Location ID: 318225



Photo 3 WH sign.

Photo 4 Dead vegetation(debris) around the WH.

Inspection Photos
Location Name: Guadagnoli 2
Location ID: 318225



Photo 5 Ancillary equip. overrun with vegetation



Photo 6 Dead vegetation & trash inside the wellsite fencing.

Inspection Photos
Location Name: Guadagnoli 2
Location ID: 318225



Photo 7 Dead vegetation all along wellsite fencing.



Photo 8 Vegetation & trash all around the wellsite.