

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

08/08/2024

Document Number:

403882777

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 99999 Contact Person: Jacob Harter
Company Name: OLD OPERATORS - STATUS UNKNOWN Phone: (970) 946-3761
Address: SEE COMMENT LINE IN WELL Fax: ( )
City: XXXXXXXX State: XX Zip: Email: jharter@cottonwoodconsulting.com

Identification Information

API Number: 05 - 103-12497 ECMC Facility ID: 479212 Initial Form 19 or 27 Document number: 403266845
Facility Name: Rangely Unknown Facility Number: 33 (OWP) Facility Type: WELL
Location QtrQtr: SWSE Section: 32 Township: 2N Range: 102W Meridian:
County: RIO BLANCO Field Name: RANGELY
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: OLD OPERATORS - STATUS UNKNOWN Agent Name: Jacob Harter Title: Consultant
Phone Number: 970-946-3761 Email: jharter@cottonwoodconsulting.com

Rule 909.J Inspection Information

Date the Pit was Inspected
On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 479212 Facility Name: Rangely Unknown 33 (OWP) Facility Type:
Location: QtrQtr: SWSE Sec: 32 Twp: 2N Range: 102W Meridian: 6
County Name: RIO BLANCO Latitude: 40.093316 Longitude: -108.864802

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 121292 Document Name: Size of file in bytes: 89088 File Name: Rangely Unknown #33 (OWP) Soil Sample EDD (1).xls
SampleType: Matrix:
Facility ID: 479212 Sample ID: 660999 Sample Name: Rangely Unknown #33 (OWP) (1) Sample Date: 05/21/2024
Collection Point: WellHead Matrix: SOIL Pre Post: Remediation
Project Number: Remediation Number: 26683 Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2405282-01

Sample Facility Attachment:

No Facility Attachment

**Sample ECMC Well Related:**

No Sample ECMC Well Related Information Provided.

**General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
Engineer	The data submitted by the operator can be accessed through COGIS data system.	08/20/2024
Total: 1 comment(s)		