

## Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/35NWNE

Location ID: 336045

Date: 8/16/2024



Entrance to location - Photo #04667



Location - Photo #04740



Inspection Photos  
Location: CHEVRON USA INC SKR-65S98W/35NWNE  
Location ID: 336045  
Date: 8/16/2024



Wellheads - Photo #04668



Plugged Well - Photo #04671



Inspection Photos  
Location: CHEVRON USA INC SKR-65S98W/35NWNE  
Location ID: 336045  
Date: 8/16/2024



Plugged Well - Photo #04672



Bulk Manifold - Photo #04685




## Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/35NWNE

Location ID: 336045

Date: 8/16/2024



Bulk Manifold - Photo #04686



Air receivers/out of service - Photo #04698



Inspection Photos  
Location: CHEVRON USA INC SKR-65S98W/35NWNE  
Location ID: 336045  
Date: 8/16/2024



Sand Separator/out of service - Photo #04701



Sand Separator/out of service - Photo #04703



**Inspection Photos**  
**Location: CHEVRON USA INC SKR-65S98W/35NWNE**  
**Location ID: 336045**  
**Date: 8/16/2024**



**Test Separator - Photo #04713**



**Bulk Separator - Photo #04717**



## Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/35NWNE

Location ID: 336045

Date: 8/16/2024



Line heaters/out of service - Photo #04725



Exhaust stack/out of service - Photo #04738



**Inspection Photos**  
**Location: CHEVRON USA INC SKR-65S98W/35NWNE**  
**Location ID: 336045**  
**Date: 8/16/2024**



**Tank battery - Photo #04739**



**SW corner of location - Photo #04754**



## Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/35NWNE

Location ID: 336045

Date: 8/16/2024



NW corner of location - Photo #04755



Stockpiled soils with no BMP's - Photo #04746



**Inspection Photos**  
**Location: CHEVRON USA INC SKR-65S98W/35NWNE**  
**Location ID: 336045**  
**Date: 8/16/2024**



**Stockpiled soils with no BMP's - Photo #04747**



**Debris - Photo #04674**



## Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/35NWNE

Location ID: 336045

Date: 8/16/2024



Debris - Photo #04675



Debris - Photo #04676



Inspection Photos  
Location: CHEVRON USA INC SKR-65S98W/35NWNE  
Location ID: 336045  
Date: 8/16/2024



Debris - Photo #04677



Debris - Photo #04678



Inspection Photos  
Location: CHEVRON USA INC SKR-65S98W/35NWNE  
Location ID: 336045  
Date: 8/16/2024



Debris - Photo #04679



Debris - Photo #04680



Inspection Photos  
Location: CHEVRON USA INC SKR-65S98W/35NWNE  
Location ID: 336045  
Date: 8/16/2024



Debris - Photo #04682



Debris - Photo #04688



## Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/35NWNE

Location ID: 336045

Date: 8/16/2024



Debris - Photo #04689



Debris - Photo #04707



## Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/35NWNE

Location ID: 336045

Date: 8/16/2024



Debris - Photo #04727



Debris - Photo #04728



## Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/35NWNE

Location ID: 336045

Date: 8/16/2024



Debris - Photo #04729



Debris - Photo #04731



**Inspection Photos**  
**Location: CHEVRON USA INC SKR-65S98W/35NWNE**  
**Location ID: 336045**  
**Date: 8/16/2024**



**Debris - Photo #04733**



**Debris - Photo #04735**



## Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/35NWNE

Location ID: 336045

Date: 8/16/2024



Debris - Photo #04749



Debris - Photo #04750



## Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/35NWNE

Location ID: 336045

Date: 8/16/2024



Debris - Photo #04751



Debris - Photo #04761



## Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/35NWNE

Location ID: 336045

Date: 8/16/2024



Debris - Photo #04762



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources