

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403894538

Date Received:
08/20/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

CAERUS

COGCC.inspections@caerusoilandgas.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302592

Inspection Date: 08/14/2024

FIR Submit Date: 08/16/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335574

Location Name: N. PARACHUTE-65S95W Number: 27NWNW County: _____

Qtrqtr: NWN Sec: 27 Twp: 5S Range: 95W Meridian: 6
W

Latitude: 39.590261 Longitude: -108.046892

FACILITY - API Number: 05-045- -00 Facility ID: 335574

Facility Name: N. PARACHUTE-65S95W Number: 27NWNW

Qtrqtr: NWN Sec: 27 Twp: 5S Range: 95W Meridian: 6
W

Latitude: 39.590261 Longitude: -108.046892

CORRECTIVE ACTIONS:

1 CA# 197784

Corrective Action: Secure gas meter house to comply with Rule 608.e.

Date: 08/21/2024

Response: CA COMPLETED

Date of Completion: 08/20/2024

Operator Comment: Closed separator door to prevent wildlife entry

ECMC Decision: _____

ECMC Representative:	
-------------------------	--

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joey Gracey Signed: _____

Title: Compliance Date: 8/20/2024 11:26:39 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403894551	Closed separator door to prevent wildlife entry

Total Attach: 1 Files