

Operator: 8 North

Location Name: TROSTEL-611N61W 32SWNW

Loc ID: 410119

Inspection: 684904653



Exhibit A



Exhibit B



Exhibit C

CA: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

CA Resolution: Operator has provided photo evidence that the stained soil in the engine and exhaust has been removed or remediated to comply with the 600 series.



Exhibit A



Exhibit B

CA: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

CA Resolution: Operator has provided photo evidence that the stained soil in treater house has been removed or remediated to comply with the 600 series.