

Caerus Piceance LLC
Piceance Creek Unit-62S97W 13SWNE
Location ID: 335689



When sign is replaced additional information is required

When sign is replaced additional information is required

Caerus Piceance LLC
Piceance Creek Unit-62S97W 13SWNE
Location ID: 335689



Debris



Debris

Caerus Piceance LLC
Piceance Creek Unit-62S97W 13SWNE
Location ID: 335689



Production pad looking Northwest



Production pad looking Southeast

Caerus Piceance LLC
Piceance Creek Unit-62S97W 13SWNE
Location ID: 335689



Well pad from Southeast corner



Well pad from Southwest corner

Caerus Piceance LLC
Piceance Creek Unit-62S97W 13SWNE
Location ID: 335689



Well pad from Northwest corner



Well pad from Northeast corner