

Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/36NWSW

Location ID: 336048

Date: 8/16/2024



Entrance to location - Photo #04770



Location - Photo #04808

Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/36NWSW

Location ID: 336048

Date: 8/16/2024



Workover Rig - Photo #04771



Wellheads - Photo #04773

Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/36NWSW

Location ID: 336048

Date: 8/16/2024



Rig tanks - Photo #04782



Rig pump - Photo #04795

Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/36NWSW

Location ID: 336048

Date: 8/16/2024



Bulk manifold - Photo #04798



Bulk manifold - Photo #04799

Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/36NWSW

Location ID: 336048

Date: 8/16/2024



Separator/Wildlife hazard - Photo #04802



Tank battery - Photo #04807

Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/36NWSW

Location ID: 336048

Date: 8/16/2024



NW corner of location - Photo #04828



NE corner of location - Photo #04831

Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/36NWSW

Location ID: 336048

Date: 8/16/2024



SE corner of location - Photo #04832



SW corner of location - Photo #04833

Inspection Photos
Location: CHEVRON USA INC SKR-65S98W/36NWSW
Location ID: 336048
Date: 8/16/2024



Wildlife hazard - Photo #04779



Wildlife hazard - Photo #04781

Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/36NWSW

Location ID: 336048

Date: 8/16/2024



Wildlife hazard - Photo #04786



No labeling - Photo #04791

Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/36NWSW

Location ID: 336048

Date: 8/16/2024



PRV line not capped - Photo #04803



PRV line not capped - Photo #04804

Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/36NWSW

Location ID: 336048

Date: 8/16/2024



Stockpiled soils with no BMP's - Photo #04812



Stockpiled soils with no BMP's - Photo #04818

Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/36NWSW

Location ID: 336048

Date: 8/16/2024



Stockpiled soils with no BMP's - Photo #04821



Debris - Photo #04794

Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/36NWSW

Location ID: 336048

Date: 8/16/2024



Debris - Photo #04814




Debris - Photo #04815

Inspection Photos
Location: CHEVRON USA INC SKR-65S98W/36NWSW
Location ID: 336048
Date: 8/16/2024



Debris - Photo #04822



Debris - Photo #04823

Inspection Photos
Location: CHEVRON USA INC SKR-65S98W/36NWSW
Location ID: 336048
Date: 8/16/2024



Debris - Photo #04824



Debris - Photo #04825

Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/36NWSW

Location ID: 336048

Date: 8/16/2024



Debris - Photo #04826



Debris - Photo #04829

Inspection Photos

Location: CHEVRON USA INC SKR-65S98W/36NWSW

Location ID: 336048

Date: 8/16/2024



Debris - Photo #04834



Debris - Photo #04835