

# Inspection Photos

API: 017-06625

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 8/19/2024

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



## Inspection Photos



**Photo 2.** Facing east along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 3.** Facing northeast toward the wellsite. There is impacted soils from the previous spill that were not cleaned up.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 4.** It appears there was sand spread on top of the spill which was not cleaned up per the rules. There is a new leak at the wellhead shown at red arrow.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 5.** The pumpjack engine is still leaking oil and there is stained soils around the base.





## Inspection Photos



**Photo 6.** It appears there was sand spread on top of the spill which was not cleaned up per the rules. There is still oily soils that remain underneath the sand that was placed over the stained soils.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06625 | Date: 8/19/2024



## Inspection Photos



**Photo 7.** Facing west toward the location. There is evidence of water pooling at the east side of the pumpjack with no proper drainage. There is a piece of the pumpjack laying on the ground.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06625 | Date: 8/19/2024