

# Inspection Photos

API: 017-06410

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 8/19/2024

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and vehicles shall not drive outside of the access road boundary. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06410 | Date: 8/19/2024



## Inspection Photos



**Photo 2.** Facing southwest toward the wellsite. The fence around the solar panel is not maintained.



## Inspection Photos



**Photo 3.** The well sign is faded and not legible. There is oil stained soils at red arrow. There is a chemical barrel with no secondary containment..

