

Inspection Photos

Location Name: SLW GREEN STATE-65N63W/18NESE

Location #: 330538



Photo #1

SLW Green State BB 18-09 (123-19257) Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: base plug



Photo #2

SLW Green State BB 18-09 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: base plug

Site safety signage



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: SLW GREEN STATE-65N63W/18NESE
Location #: 330538



Photo #3

SLW Green State BB 18-09 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: base plug
Wellsite entrance

Photo #4

SLW Green State BB 18-09 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: base plug
JSA: 2024-08-19



Inspection Photos

Location Name: SLW GREEN STATE-65N63W/18NESE

Location #: 330538



Photo #5

SLW Green State BB 18-09 Battery site

Plugged & Abandoned | PA

Plugging Ops; Cementing: base plug

Battery sign

prior photo



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources