

Inspection Photos

API: 017-06457

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 8/19/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the wellsite. The sign has fallen over and must be reinstalled.



Inspection Photos



Photo 2. There is a buried barrel that needs to be removed and oily netting both shown at red arrows.



Inspection Photos



Photo 3. There is dark oily soils and a tipped over chemical drum. Stained soils must be cleaned up and unused equipment removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06457 | Date: 8/19/2024