

Inspection Photos
Location Name: Horsetail 07 CPB
Location ID: 439324



Energy and Carbon Management Commission
40.85569, -103.79718, 4853.7ft
08/14/2024 14:24:11



Energy and Carbon Management Commission
40.85638, -103.79715, 4853.2ft
08/14/2024 14:24:40

Photo 1 – Heater Treaters

Photo 2 – Gas Meters

Inspection Photos
Location Name: Horsetail 07 CPB
Location ID: 439324



Photo 3 – Production Equipment



Photo 4 – VRTs

Inspection Photos
Location Name: Horsetail 07 CPB
Location ID: 439324



Photo 5 – Tank Battery Signs



Photo 6 – Tank Battery

Inspection Photos
Location Name: Horsetail 07 CPB
Location ID: 439324



Photo 7 – Tank Battery



Photo 8 – Water LACTs

Inspection Photos
Location Name: Horsetail 07 CPB
Location ID: 439324



Photo 9 – LACT



Photo 10 – ECD and Flare

Inspection Photos
Location Name: Horsetail 07 CPB
Location ID: 439324



Photo 11 – Production Equipment



Photo 12 – Compressors

Inspection Photos
Location Name: Horsetail 07 CPB
Location ID: 439324



Photo 13 – Heater Treaters