

# Inspection Photos

Loc: 321579

Operator: CITATION OIL & GAS CORP

Inspection Date: 8/19/2024

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast toward wellsite location.



## Inspection Photos



**Photo 2. Photo from previous inspection.** There is oil stained soils around the wellhead that must be cleaned up. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321579 | Date: 8/19/2024



## Inspection Photos



**Photo 3.** There is oil stained soils around the wellhead that must be cleaned up. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321579 | Date: 8/19/2024



## Inspection Photos




**Photo 4.** There is oily soils at the base of the shed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321579 | Date: 8/19/2024

## Inspection Photos



**Photo 5.** View of inside the shed shows a leak occurring from the pumpjack engine. This needs to be controlled and cleaned up. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:321579 | Date: 8/19/2024